

Fleet Leasing

ASSESSMENT REPORT OF PROPERTY DAMAGE TRAFFIC ACCIDENTS

ASSOCIATION OF THE INSURANCE AND REINSURANCE COMPANIES OF TURKEY

1	Date of Accident	Time
	14.09.2013	116:55

2	City: Istanbul	District: Dikilitas
Accident Location	County: Besiktas	Main Street: Ataturk
	Quarter: Ihlamur	Street: Manzara

3 Eyewitnesses

Full Name	Address	Phone No:
Ali-----	Inonu Mah. Papatya Sok. No 30 Besiktas /Istanbul	05-----

		A	7- Put Mark (x) to Appropriate Boxes	B		
VEHICLE A			Violation of red light	X	VEHICLE B	
4	Driver Information		Entry into the highway marked with 'Vehicles Are Not Allowed' sign		4	Driver Information
Full Name: Mehmet -----			Entry into the road used by traffic coming from opposite direction		Full Name: Ahmet-----	
REPUBLIC OF TURKEY ID No: 4306			Overtaken at 'No passing' (overtaking ban) place		REPUBLIC OF TURKEY ID No:----- ----	
Driving License No. and Class: 78467-B			Disobey switch priority at a crossroad	X	Driving License No. and Class: 44231-B	
Taken Location (city / county): Istanbul/Sisli			Pass at 'Stop' sign of authorized officer		Taken Location (city / county): Istanbul/Bakirkoy	
Address: Balmumcu Mah. Ari Sok. No: 20/8 Besiktas / Ist.			Slammed into the back of the front vehicle driving in the same direction and same lane		Address: Atakent Mah. Ihlamur No: 28 Kucukcekmece / Ist.	
Tel No: 05-----			Disobey to turn to right rules		Tel No: 05-----	
5	Vehicle Information		Disobey to turn to left rules		5	Vehicle Information
Chassis No: AAABBB11112222333			Disobey to back maneuver rules		Chassis No: CCCDD44445555666	
Brand and Model: Audi A5			Disobey to passing (overtaking) rules		Brand and Model: Opel Corsa	
Plate No: 34 DRD 123			Disobey to right of way rules		Plate No: 34 ABC 912	
Usage: Company			Disobey to parking rules		Usage:	
6	Traffic Insurance Policy		Disobey to standing rules		6	Traffic Insurance Policy

First Name Surname of Insured: Derindere Tourism	Hit a vehicle parked according to rules			Full Name of Insured: Ahmet -----	
REPUBLIC OF TURKEY ID / Tax ID:	km / h	Speed Condition	km / h	REPUBLIC OF TURKEY ID / Tax ID:	
Title of Insurance Company: XYZ Insurance	m.	If detected, the brake mark length	m.	Title of the Insurance Company: ABC Insurance	
Agency No: 4207	8- If car has Green Card, section to be filled in			Agency No: 1234	
Policy Number: 12345678	VEHICLE A	VEHICLE B	Policy Number: 13579111		
TRAMER Document No: 987654	Green Card No:	Green Card No:	TRAMER Document No: 246810		
Policy Start-to-Finish Date: 14.07.2013-2014	Country:	Country:	Policy Start-to-Finish Date: 12.05.2012-2013		
9	Vehicle's first point of impact, show with an arrow @.	Passport No:	Passport No:	9	Vehicle's first point of impact, show with an arrow @.

Front
Rear

Front
Rear

10 Draw a draft of place and moment of crash.

Papatya Sok.
34 DRD 123 (Vehicle A)

34 ABC 912 (Vehicle B)

11 Driver Feedback

When I started off after green light turned on, vehicle with plate no. 34 ABC 912 could not stop at red light and hit my vehicle with plate no. 34 DRD 123.

Driver Feedback 11

I could not stop at the red light, and hit vehicle with plate no. 34 DRD 123 with my vehicle with plate no. 34 ABC 912.

12 Signatures of Drivers 12

Signature
Signature

